


SIEVE ANALYSIS FL DEP ROSS.GPJ FL DEP ROSS.GDT 1/29/05



Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
ABCD-01-23 #1	—●—	-15.1	SP	#200 - 1.31 #230 - 1.30	1.00	25.00	2.64	2.57	-1.97	13.22	0.38	Project Name:	gINT Test Project
Comments: lab remarks												Analysis Date:	04-27-04
Depths and elevations based on measured values												Analyzed By:	Y. Me
<b>COMPANY LOGO HERE</b>							ACME Coastal Consultants 1234 Main Street Sunny Place, Florida 32999 ph (000) 555-1234 fax (000) 555-4321					Easting (X, ft):	406,020
												Northing (Y, ft):	1,162,598
												Horizontal System:	HARN
												Vertical System:	NAVD 29