

Logo

ACME Consulting
1234 Main Street

Telephone: (000) 555-1234
Fax: (000) 555-4321

LOG OF BOREHOLE B-1

Project: gINT Example
Location: Somewhere, USA
Date Drilled: 11/4/2003
Logged By: A. Bore

Depth Feet	Description	Log	Elev. Depth	Samples	PL	Moisture	LL	N-Value ▲	Installations/ Comments
0	<u>FILL</u> : LEAN CLAY with some fine sand and fine gravel, light brown, dry		123.4 0.0	1					Bentonite grout Schedule 40 PVC pipe
5				2					Bentonite pellets
10	<u>SANDY CLAY</u> : low to moderate plasticity, fine to medium sand, brown, moist with fine to medium gravel		113.4 10.0	3					Schedule 40 PVC slotted (0.020") pipe with Monterey sand backfill
15	<u>CLAYEY GRAVEL</u> : fine to coarse, moderate plasticity, gray and brown mottled, saturated		108.4 15.0	4					Bentonite pellets
20	<u>LIMESTONE</u> moderately strong, moderately weathered, tan		103.4 20.0	5					Cement grout Cave-in
25				R-1					
30	Bottom of borehole at 30 feet.		93.4 30.0	R-2					

LOG A.GWGN02.LOG A.GWGN02.GPJ LOG A.GWGN02.GDT 7/21/04